

508

Accident No.	
Date	19-4-70
Checked by	
Analyzed by	
Copied for Wright	
Filed by	
Notes	

98719-440FS

WAR DEPARTMENT
A. A. F. FORM NO. 14
(Revised May 15, 1942)

ACCIDENT NO.

WAR DEPARTMENT
U. S. ARMY AIR FORCES
REPORT OF AIRCRAFT ACCIDENT

(1) Place **San Giovanni Air Base, Italy.** (2) Date **15 March 1945** (3) Time **0740A**
 AIRCRAFT: (4) Type and model **B-24G** (5) A. F. No. **42-7836V** (6) Station **APO 520**
 Organization: (7) **15th Air Force** (8) **454th Bomb Gp** (9) **737th Bomb Squadron (H)**
 (Command and Air Force) (Group) (10) (11) (12) (13) (14) (15) (16) (17) (18) (19) (20)

PERSONNEL

DEPT. (10)	NAME (Last name first) (11)	RATING (12)	SERIAL NO. (13)	RANK (14)	PROMOTED CLASS (15)	BRANCH (16)	ARMY FORCE OR COMMAND (17)	RESULTANT PERSONNEL (18)	USE OF PARACHUTE (19)
P	Mullins, Lynn D.	P	O-721172	2nd Lt	18 ✓	AC	16thAF	None	No
CP	Walker, Gene A.	P	O-2084127	2nd Lt	18 ✓	AC	15thAF	None	No
N	Hart, Clyde L.	N	O-928430	2nd Lt	18	AC	15thAF	None	No
E	Masterson, John (nat)	E	16073979	T/Sgt	20	AC	15thAF	None	No
R	Duvall, Elven E.	R	16113162	T/Sgt	20	AC	15thAF	None	No
G	Zika, Joseph P.	G	36297435	S/Sgt	38	AC	15thAF	None	No
G	Sippola, Charles A.	G	35917966	S/Sgt	38	AC	15thAF	None	No
G	Tietjen, Charles H.	G	12153861	S/Sgt	20	AC	15thAF	None	No
G	Spreadbury, Jack W.	G	15132522	S/Sgt	20	AC	15thAF	None	No

PILOT CHARGED WITH ACCIDENT

(20) **Mullins Lynn** (21) **O-721172** (22) **2nd Lt** (23) **18** (24) **AC**
 (Last name) (First name) (Middle initial) (Serial number) (Rank) (Personnel class) (Branch)

Assigned (25) **15th Air Force** (26) **454th Bomb** (27) **737th Bomb Sq. (H)** (28) **APO 520**
 (Command and Air Force) (Group) (Squadron) (Station)

Attached for flying (29) **15th Air Force** (30) **454th Bomb** (31) **737th Bomb Sq. (H)** (32) **APO 520**
 (Command and Air Force) (Group) (Squadron) (Station)

Original rating (33) **Pilot** (34) **15-A-44** Present rating (35) **Pilot** (36) **15-A-44** Instrument rating (37) **20-B-44**
 (Rating) (Date) (Rating) (Date) (Rating) (Date)

FIRST PILOT HOURS:
(at the time of this accident)

(38) This type	18840	(42) Instrument time last 6 months
(39) This model	1440	(43) Instrument time last 30 days
(40) Last 90 days	7140	(44) Night time last 6 months
(41) Total	18940	(45) Night time last 30 days

AIRCRAFT DAMAGE

DAMAGE	1	2	3	4
(46) Aircraft	W			
(47) Engine(s)		3	3	
(48) Propeller(s)		3	3	

(49) LIST OF DAMAGED PARTS

(50) Weather at the time of accident **Ceiling and Visibility unlimited.**

(51) Was the pilot flying on instruments at the time of accident **No**

(52) Cleared from **APO 520** (53) To **Return** (54) Kind of clearance **Contact**

(55) Pilot's mission **Combat Bombing.**

(56) Nature of accident **Airplane ran into a ditch and struck culvert while taxiing.**

(57) Cause of accident **Brake malfunction.**

(58) Has form 54 been submitted? **No.**

RESTRICTED

DESCRIPTION OF ACCIDENT

(Brief narrative of accident. Include statement of responsibility and recommendations for action to prevent repetition)

After aircraft was checked and engines started, difficulty was experienced in attempting to taxi out. Excessive power was used to cause the brakes to release. After aircraft had been taxied approximately 100 yards on the taxiway the right brake seemed to pull aircraft to the right, and the left brake was ineffective. The pilot then applied more right brake to cause the aircraft to go into a field where he stopped it safely without damage. Inspection showed the left brakes to be locked with the pedal depressed, and one of the right brakes locked. The brake lines were bled by the Flight and Crew Chief and air was found in the left brake system. After being bled, the brakes tested satisfactorily and the aircraft was taxied onto the taxiway. After taxiing approximately 100 yards, the aircraft again was apparently dragged to the right by right brake. The left brake was again ineffective and the pilot applied full power to the right engines in an attempt to keep the aircraft straight on the taxiway until a culvert had been passed, however, the right wheel went into a ditch and the aircraft went off the taxiway. The right gear was snapped off in the culvert and the nose wheel broken off before the aircraft came to a stop.

The aircraft was taxied with controls locked, and both accumulators showed 1000 pounds pressure after the accident. The same difficulty with the brakes was experienced by another pilot while taxiing the aircraft about one week before this accident and the brake system was thoroughly checked at this time and no malfunction found.

It is the opinion of the accident board that the accident occurred through no fault of the pilot. Investigation and examination of the aircraft following the accident has disclosed no defects in the system which might have caused the accident except for the presence of air in the hydraulic lines.

There are no recommendations at this time. Examination of the aircraft is being continued.

Robert E. Dunlap
ROBERT E. DUNLAP,
Captain, Air Corps,
Investigating Officer.

William E. Kavasch
WILLIAM E. KAVASCH,
Major, Air Corps,
Investigating Officer.

William R. Grady
WILLIAM R. GRADY,
Major, Air Corps,
Investigating Officer.

William R. Large Jr.
WILLIAM R. LARGE, Jr.,
Lt. Col., Air Corps,
Senior Officer - Aircraft
Accident Investigation Board.

Signature

Date 19 March 1945.

三一

REVIEWS


卷之三

卷之三

THE GOVERNMENT
OF A
COLONY,
T.S.

WAR DEPARTMENT
A. A. F.
FORM NO. 1 A
5-2-42

FLIGHT REPORT - ENGINEERING

INSPECTION STATUS				SERVICING AT STATION OF TAKE-OFF (CHECK IMMEDIATELY BEFORE TAKE-OFF)											
	DATE OF OR HOURS DUE	BY	STATION	SERVICE	FUEL (GALLONS)	OIL (QUARTS)				RADIATOR CHECKED					
PREFLIGHT	3-15-40	P	A.P.O. #520	1ST	SERV- ICED	IN TANKS	NO 1	NO 2	NO 3	NO 4	SERV- ICED				
DAILY	3-15-40	P		2ND	SERV- ICED	IN TANKS	---	128	---	128	SERV- ICED				
25 HOURS	616:20			3RD	SERV- ICED	IN TANKS	---	128	---	128	SERV- ICED				
50 HOURS	615:00			4TH	SERV- ICED	IN TANKS	---	128	---	128	SERV- ICED				
100 HOURS	615:00			5TH	SERV- ICED	IN TANKS	---	128	---	128	SERV- ICED				
INSPECTION OF AUXILIARY EQUIPMENT				STATUS TODAY	EXPLANATION: #1 & #2 CarbAir Temp Inop(nis) Ball Turret Trouble Light Inop (nis) Top Turret Azimuth Crank Handle Out (nis) #2 Generator Removed										
EQUIPMENT	SYMBOL	INSPECTED BY	STATION	1.	2.	3.	4.								
BOMBARDMENT	P	Powers	A.P.O. #520												
GUNNERY	P	Powers													
CHEMICAL															
COMMUNICATIONS	JAM	MacLeod													
PHOTOGRAPHIC															
NAVIGATION	P	Padon													
Carpet	F	Faber													
REMARKS: PILOTS AND MECHANICS - SEE INSTRUCTIONS INSIDE FRONT COVER.				RELEASED FOR FLIGHT											
3/Lynn D. Mulline															
AIRCRAFT AND ENGINE TIME RECORD (ENTER IN HOURS AND MINUTES)															
ENGINE	NO. 1	NO. 2	NO. 3	NO. 4											
HOURS TO DATE	181:00	192:35	181:00	237:20											
HOURS TODAY															
TOTAL															
OIL CHANGE DUE	100 Hour Inspection														
CND, CLEAN- ING DUE	25 Hour Inspection														
AIRCRAFT	HOURS TO DATE	591:20													
	HOURS TODAY														
	TOTAL														
<u>A TRUE COPY:</u>															
 ROBERT N. SALES, Captain, Air Corps, Ass't Operations OFFICER.															
ENGINE DATA (1) O-133-64468 Serial number (2) GP-316550 Serial number (3) GP-316572 Serial number (4) GP-3165078 Serial number				AIRCRAFT DATA E-24-0 Aircraft number 42-10816 Aircraft serial no.				AIRCRAFT ORG. DATA 15th AF 30th Wing 424th Bom (B) 773d Bomb (B) Squadron no. and type				215-42 Date 5/20/40 Month Year 1000 hrs Time S/Sgt. Pedee Name 1st Lt. John W. Mulline Name			

R E D E R E L E A S E D

HEAD, PARTIES
737TH BOMBARDMENT GROUP (H), AAF
454TH BOMBARDMENT GROUP (H), AAF
AC 520 U. S. ARMY

15 March 1945

S T A T E M E N T

After the morning pre-flight and finding everything in order, we started engines and attempted to taxi out for take-off but found that the brakes were locked. I broke the brakes loose by adding power and pressing the brake pedals three or four times. After taxiing approximately one hundred (100) yards, the right brake locked, pulling the airplane off of the taxi strip. I stopped the airplane before any damage was done. We cut the engines, got out of the airplane to examine the brakes and found them locked with the exception of the outboard brake on the right wheel. The lines were drained by a Flight Chief, and operation of the brakes was checked visually. I inspected the landing gear and the condition of the airplane and found no damaged parts. There was nothing to indicate that the brakes would fail again as I operated them several times checking them by noting the pressure in the accumulators and moving the ship to see if they were locked. During taxiing the ship started veering to the right slowly. I applied power on the right side with left brake. The ship traveled straight after I had completed several minor corrections with brake to avoid excessive speed. The airplane veered to the right again and I applied left brake to correct the turn, instead of throttle, to avoid speed and the danger of over correcting which would necessitate further use of brakes. The brake made no apparent effect on the aircraft. After trying to make the brake operate several times, I cut the power in an attempt to stop the aircraft, but this seemed only to cause the airplane to veer more to the right. As a last resort, I added full power to number three and number four engines in an attempt to straighten the aircraft out. This failed, so I gave the order to hit the crash bar and abandon the aircraft immediately after the right main gear and nose wheel buckled.

Lynn D. Mullins
LYNN D. MULLINS,
2nd Lt., Air Corps,
Pilot.

R E D E R E L E A S E D

R E S T R I C T E D

HEADQUARTERS
737TH BOMBARDMENT SQUADRON (H), USAF
454TH BOMBARDMENT GROUP (H), USAF
AFB 520 U.S. ARMY

15 March 1945

S T A T E M E N T

After performing the morning pre-flight, in which everything checked to operational requirements, we started the engines and checked all instruments and engines. We tried to taxi out of the hard stand but the brakes were released only after excessive power was drawn on four engines. The brakes were working until we had proceeded about one hundred and fifty (150) yards. At this time we lost the left wheel brake and were forced to run out into the grass. We cut all four engines, got out of the airplane and inspected all brakes. They all appeared stuck except for the right out-board. The three brakes that appeared stuck were not, on further inspection, in the fully expanded position. The Crew Chief proceeded to fix the hydraulic system and got them into proper working order. The Flight Chief then gave his report that they were in proper working order. The Pilot and I also inspected the brakes and found them to be working properly. We started the engines again and taxied back on to the strip and started for the south end of the runway. The brakes were functioning properly for approximately one hundred and fifty (150) yards, when they suddenly went out once more. We veered to the right side of the taxi strip and were heading for a culvert. The Pilot added power to number three and four engines in order to steer the plane to the left and avoid the culvert. The added power failed to correct the course of the airplane and seeing that we could not possibly miss the culvert, I hit the crash bar. We hit the culvert and came to a sudden halt after the right landing gear collapsed. The crew members were ordered to abandon the ship as quickly as possible. Number one and number two engine failed to be cut off by the crash bar so the Pilot and I cut all switches and throttles and abandoned the airplane.

Gene A. Walker
GENE A. WALKER,
2nd Lt., Air Corps,
Co-Pilot.

R E S T R I C T E D

REBELLICATED

HEADQUARTERS

737TH BOMBARDMENT SQUADRON (H), AAF
454TH BOMBARDMENT GROUP (H), AAF
ACG 520 U.S. ARMY

16 March 1945

STATEMENT

I was the Pilot on airplane number 42-78316 on 12 March 1945. On this particular date, I flew a practice mission and had considerable trouble with the brakes. The left brake was very weak and slow in functioning. While taxiing to take-off position the right brake seemed to grab all the way. After the mission, while taxiing to the hardstand, the right brake stuck and the left was not sufficient to hold the plane straight. The airplane ran into a ditch.

Loran I. Fleming
LORAN I. FLEMING,
2nd Lt., Air Corps,
Pilot.

REBELLICATED

REMARKS

HEADQUARTERS
737TH BOMBARDMENT SQUADRON (H), AAF
454TH BOMBARDMENT GROUP (H), AAF
AC 520 U.S. ARMY

15 March 1945

BATTLE HISTORY

After we had started our engines, we tried to taxi out of the revetment but the brakes stuck and we had to use power to break them loose. After getting the brakes loose, we began taxiing down the strip to the north end of the runway. After taxiing a short distance the brakes on the right wheel seemed to lock and pulled us off the strip into a field. We stopped and shut off the engines. I got out and looked at the brakes and found they were on except the right outboard. The Flight Chief came over to the aircraft and took off the bleeder nut and bled the brake lines. He and the Crew Chief then tried the brakes and they operated normally. The Flight Chief then said that the brakes were alright. We taxied back onto the strip and started for the south end of the runway. The aircraft then started to veer to the right toward a culvert. The Pilot revved up number three and number four engines in an attempt to avoid the ditch; however, we kept heading for the ditch. We then ran off the strip and hit the culvert which knocked off the right main gear and the nose wheel. The Pilot and Co-Pilot then shut off the mixtures and batteries after the Co-Pilot had hit the crash bar. We then abandoned the airplane.

John Masters
JOHN MASTERS,
T/Sgt., 16073979,
Engineer.

REMARKS

R E S T R I C T E D

557TH AIR SERVICE SQUADRON
43RD AIR SERVICE GROUP
AFB 320, U. S. ARMY

16 March 1945

S T A T E M E N T

I inspected the left brake on airplane number 42-78316 on 16 March 1945 and found it to be worn badly. Signs of crystallization show that the brake at one time had been excessively hot. One brake expander tube spring was broken. Brake drums were scored.

Gerald J. Post
GERALD J. POST
M/Sgt., 6936268
Inspector.

R E S T R I C T E D

R E B T R E F C T E D

HEADQUARTERS
737TH BOMBARDMENT SQUADRON (H), AAF
454TH BOMBARDMENT GROUP (H), AAF
AMC 520 U.S. AIR FORCE

16 March 1945


S T A T E M E N T

I was on duty the morning that aircraft number 42-78316 ran into a ditch while taxiing out for take-off. The aircraft taxied out of the revetment and after going about three hundred (300) yards the left brake locked. I went down and bled the brake system and found that the left brake had an air lock. After removing the air lock, we pumped the brakes six or seven times to make sure of normal operation. The brakes worked normally prior to taxiing into a ditch and striking a culvert.


Joe George
Joe George,
M/Sgt., Air Corps,
Flight Chief.

R E B T R E F C T E D

THIS PAGE IS DECLASSIFIED IAW EO 13526



(44-80444) B-24 C-42 7816-737745 090000



THIS PAGE IS DECLASSIFIED IAW EO 13526

HEADQUARTERS
454TH BOMBARDMENT GROUP (H), AAF
APC 520
US ARMY

E/RD/tz

20 March 1945

SUBJECT: Accident Report.

TO : Chief, Flying Safety, Winston-Salem, North Carolina.

In compliance with AAF Regulation 62-14A, dated 28 January 1944,
transmitted herewith is the completed AAF Form 14 and inclosures pertaining
to aircraft accident on 15 March 1945, of B-24G AF No. 42-76316.

For the Commanding Officer,

Peter J. Haas
for JOSEPH MINOTTY,
Major, Air Corps,
Adjutant.

11 Inclos:

- Incl 1 - AAF Form 14.
- Incl 2 - AAF Form 1.
- Incl 3 - AAF Form 1A.
- Incl 4 - AAF Form 205.
- Incl 5 - Statement of 2nd Lt. Mullins.
- Incl 6 - Statement of 2nd Lt. Walker.
- Incl 7 - Statement of 2nd Lt. Fleming.
- Incl 8 - Statement of T/Sgt. Masters.
- Incl 9 - Statement of M/Sgt. Post.
- Incl 10 - Statement of M/Sgt. George.
- Incl 11 - Photos.